

For Catalog of Parts and Assembly Units
(KDS) see the Table

Q-ty of sheets

1

Sheet

GROUND: Notification of change VK 1200-1547-01 dd. 30.05.2022.

Bulleting Y4R 2026-4	TRACTOR MODEL 1025/1025.4/1025.4K/1025.5/1025.6/1220.1/1220.5/1220.6/ 1220.7/1221/1221.4/1221.5/1221.6
--------------------------------	----------------------------------------------------------------------------------------------------------------------

Annotation:

Replacement of the 115K5 GOST 8338-75 ball bearing in the 80-1601050-01 shaft, which is part of the clutch housing, with a VZK 1600.01 roller bearing 6-12115 to prevent the transmission of forces through the rolling elements of the bearing during installation and to eliminate bearing failures.

Content of changes:

Group 16. Coupling clutch

Subgroup 1601. Clutch housing

The information available:
Bearing 115K5 GOST 8338-75.

Shall be replaced with:
B3K 1600.01 Bearing 6-12115.

No	Catalog of Parts and Assembly Units	Numbers of pages and positions to be changed in the KDS
1	1025-0000010 KDS (2009)	page 109, position 16
2	1025.4-0000010 KDS (2009) (1025.4 Deutz)	page 29, position 16
3	1025.4-0000010-01 KDS (MMZ 2009)	page 29, position 16
4	1025.4K-0000010 KDS (2021) (1025.4K Cummins)	page 38, position 4
5	1025.5-0000010 KDS (2013) (1025.5 MMZ)	page 47, position 16
6	1025.6-00000105 KDS (2018) (1025.6 MMZ)	page 40, position 16
7	1220.1-0000010 KDS (2011) (1220.1/1220.3/1220.4 MMZ)	page 45, position 16
8	1220.5-0000010 KDS (2013) (1220.5 MMZ)	page 51, position 16
9	1220.6-0000010 KDS (2018) (1220.6 MMZ)	page 40, position 16
10	1220.7-0000010 KDS (2020) (1220.7/1025.7/1221.7 Caterpillar)	page 41, position 4
11	1221-0000010 KDS (2009)	page 37, position 16
12	1221.4-0000010 KDS (2009)	page 30, position 16
13	1221.4-0000010-01 KDS (2009)	page 28, position 16
14	1221.5-1000010 KDS (2013)	page 44, position 16
15	1221.6-0000010 KDS (2017)	page 40, position 16
16	1221.6-00000105 KDS (2018)	page 40, position 16