

For Catalog of Parts and Assembly Units (KDS)
see the Table

Q-ty of sheets

Sheet

GROUND: notice of change VK 800-4079 dated 02.10.2025.

Bulletin Y4R 2026-7	TRACTOR MODEL	80.1/80.3/82.1/820/80X/82.3/90/92/92P/510/570/ 892/900/921/922.5/922.3/922.4/923.4/923.5/923.7/ 952.4/952.4K/952.5/952.6/952.7/1021.3/1021.5
------------------------	---------------	--

Abstract:

Replacement of the 60210 AUSH1 GOST 7242-81 ball bearing in the 70-1601060 shifter bracket, which is part of the clutch housing, with a VZK 9217.15 roller bearing 42210 (NJ 210) to prevent the transmission of forces through the rolling elements of the bearing during installation and to eliminate failures of the 60210 AUSH1 bearing.

Content of changes:

Group 16. Clutch

Subgroup 1601. Clutch housing. Shifter

Old edit:

Bearing 60210 AUSH1 GOST 7242-81.

New edit:

B3K 9217.15 Bearing 42210 (NJ 210).

Item No	Catalog designation	Numbers of pages and items to change in the catalog
1	82-0000010 KDS [2015] (80.1_80.3_82.1_820)	page 45, item 5
2	80X-0000010 KDS [2012] (80X_80X.1_100X)	page 33, item 5
3	82.3-0000010 KI [2024]	page 38, item 5
4	90-0000010 KI [2025] (90_92)	page 31, item 3
5	92П-0000010 KDS [2010] (92P)	page 37, item 5
6	510-0000010 KDS [2009]	page 75, item 5
7	570-0000010 KDS [2010]	page 89, item 5
8	892-0000010 KDS [2011]	page 39, item 5
9	900-0000010 KDS [2009]	page 51, item 5
10	921-0000010 KDS [2009-2010]	page 42, item 5
11	922.5-0000010 KDS [2013] (922.5 MMP)	page 45, item 5
12	922-0000010 KDS [2013] (922.3_922.4 MMP)	page 43, item 5
13	923.4-0000010 KDS [2014] (923.4 MMP)	page 39, item 5
14	923.5-0000010 KDS [2013] (923.5 MMP)	page 43, item 5
15	923.7-0000010 KDS [2020] (923.7 Caterpillar)	page 41, item 5
16	952.4-0000010 KDS [2009] (952.4 Deutz)	page 33, item 5
17	952.4-0000010-01 KDS [2009] (952.4 MMP)	page 33, item 5
18	952.4K-0000010 KDS [2020] (952.4K Cummins)	page 38, item 5
19	952.5-0000010 KDS [2013] (952.5 MMP)	page 53, item 5
20	952.6-0000010Б KDS [2018] (952.6 MMP)	page 43, item 5
21	952.7-0000010 KDS [2020] (952.7 Caterpillar)	page 41, item 5
22	1021.3-0000010 KDS [2010]	page 30, item 5
23	1021.5-0000010 KDS [2013] (1021.5 MMP)	page 49, item 5